CONTENTS

ACKNOWLEDGEMENTS v

PREFACE vi

CHAPTER ONE

Introduction 1

1.1 Electronics 1
1.2 Conduction — A Simple View 2
1.2.1 Superconductivity 3

CHAPTER TWO

Historical Background 5

2.1 Introduction 5

Part 1 — Printed Boards 5

2.2 Early days 5
2.2.1 Prior Art 5
2.2.2 The Birth of the Printed Circuit 6
2.2.3 The First Printed Circuit Symposium 7
2.2.4 Module Development 7
2.3 Further Development 8
2.3.1 Plated-through Hole Boards 8
2.3.2 Multilayer Boards 8
2.3.3 Additive Processes 8
2.3.4 Discrete Wired Boards 9
2.3.5 Flexible Circuits 10
2.3.6 Other PB Developments 10
2.4 Materials and Processes 10
2.4.1 Laminates 10
2.4.2 Resists and Etchants 11
2.4.3 Machining 12
2.4.4 Hole Pretreatment, Metallising and Plating 12
2.4.5 Finishes 14
2.4.6 CAD 14
2.5 In Conclusion 15
2.5.1 Printed Boards and the Environment 16
2.5.2 The Future of Printed Circuits 17

Part 2 — Electronic Components 17

2.6 General 17
2.7 1701-1800 17
2.8 1801-1900 18
2.8.1 1801-1830 18
2.8.2 1831-1860 18
2.8.3 1861-1880 19
2.8.4 1881-1900 19
2.9 1901- Present day 20
2.9.1 1901-1920 20
2.9.2 1921-1940 21
2.9.3 1941-1960 21
2.9.4 1961-1980 22
2.9.5 1981- Present day 24

Part 3 — Soldering 26

2.10 From Ancient Craft to Modern Science 26

CHAPTER THREE

Conventional Components 31

3.1 General 31
3.2 Classification 31
3.3 Resistors 32
3.3.1 Packages 32
3.3.2 Characteristics 33
3.3.3 Manufacturing Technology 35
3.3.4 Identification 37
3.3.5 Variable Resistors 40
3.4 Capacitors 40
3.4.1 Packages 40
3.4.2 Characteristics 42
3.4.3 Manufacturing Technology 43
3.4.4 Electrolytic Capacitors 46
3.4.5 Identification 49
3.4.6 Variable Capacitors 49
3.5 Semiconductor Diodes 50
3.5.1 Packages 50
3.5.2 Characteristics 51
3.5.3 Technology 56
3.5.4 Identification 58
3.5.5 Rectifiers 58
3.6 Transistors 58
3.6.1 Packages 62
3.6.2 Characteristics 63
3.6.3 Manufacturing Technology 65
3.6.4 Identification 67
3.7 Silicon Controlled Rectifiers and Thyristors 67
3.8 Optoelectronic Devices 69
3.8.1 Packages 73
3.9 Monolithic Integrated Circuits 74
3.9.1 Classification 74
3.9.1.1 Technology 74
3.9.1.2 Operating Mode 77

3.9.1.3 Function 78
3.9.1.4 Level of Integration 78
3.9.2 Manufacturing Technology 79
3.9.3 Analogue ICs 80
3.9.4 Digital ICs 82
3.9.4.1 Elementary Circuits 82
3.9.4.2 Memories 84
3.9.4.3 Microprocessors 86
3.9.4.4 ASICs 86
3.9.5 Packages 87
3.10 Hybrid Integrated Circuits 93
3.10.1 Thin Film Hybrids 94
3.10.2 Thick Film Hybrids 97
3.10.3 Packages 97

CHAPTER FOUR

Surface Mounted Components 102

4.1 General 102
4.2 Classification 103
4.3 Passive Surface Mounting Components 105
4.3.1 MELF Components 106
4.3.1.1 Resistors 107
4.3.1.2 Jumpers 108
4.3.1.3 Positive Temperature Coefficient (PTC) Resistors 108
4.3.1.4 Capacitors 108
4.3.1.5 Inductors 109
4.3.2 Mini-MELF Components 109
4.3.3 Other Cylindrical Components 110
4.3.4 Chip Components 112
4.3.4.1 Resistors 112
4.3.4.2 Jumpers 115
4.3.4.3 Thermistors 115
4.3.4.4 Ceramic Chip Capacitors 115
4.3.4.5 Microchip Capacitors 118
4.3.4.6 Chip Inductors 119
4.3.5 Other Flat Components 119
4.3.5.1 Metal Film Square Chip Resistors 119
4.3.5.2 High Power Resistors 120
4.3.5.3 Metallised Polyester Capacitors 120
4.3.5.4 Wet Type Aluminium Electrolytic Capacitors 120
4.3.5.5. Solid Aluminium Electrolytic Capacitors 123
4.3.5.6 Tantalum Electrolytic Capacitors 124
4.3.5.7 Inductors 125
4.3.5.8 Oscillators and Filters 127
4.3.6 Miscellaneous Passive Components 128
4.3.6.1 Aluminium Electrolytic Capacitors 128
4.3.6.2 Potentiometers 129
4.3.6.3 Trimmer Capacitors 129
4.3.6.4 Connectors 130
4.4 Active Surface Mounting Components 132
4.4.1 Diodes 133
4.4.2 SOT-23 135
4.4.3 SOT-89 137
4.4.4 SOT-143 137

4.4.5 SOT-223 137
4.4.6 Adapted Packages 138
4.4.7 Small Outline Integrated Circuits — SOICs 139
4.4.8 Very Small Outline Packages — VSOs 141
4.4.9 Flatpacks and Quadpacks — QFPs 141
4.4.10 Plastic Flat Packs — PFPs 143
4.4.11 Plastic Leaded Chip Carrier — PLCC 144
4.4.12 Small Outline J-leaded Package — SOJ 147
4.4.13 Leadless Ceramic Chip Carrier — LCCC 148
4.4.14 Leaded Ceramic Chip Carrier — LDCC 150
4.4.15 Other Complex Packages 150
4.4.16 Tape Automated Bonding — TAB 152
4.4.17 Chip-on-board (COB) and Multichip Modules (MCMs) 155
4.4.17.1 Chip-on-board 155
4.4.17.2 Multichip Modules 156
4.5 Supply Packaging 157
4.5.1 Bulk 157
4.5.2 Magazine 158
4.5.3 Rail and Tube 158
4.5.4 Tray or Palette 159
4.5.5 Adhesive Tape 159
4.5.6 Tape-on-reel 160
4.6 Advantages of SMT 161
4.6.1 Design Freedom 162
4.6.2 Size and Weight 165
4.6.3 Reliability 166
4.6.4 Electrical Characteristics 166
4.6.5 Effect of SMT on Automation 167
4.6.6 Cost 167
4.7 Disadvantages of SMT 168
4.8 The Future of Surface Mounting 169

CHAPTER FIVE

Manual Assembly 171

5.1 General 171
5.1.1 Manpower and Manual Assembly 172
5.2 Low Volume Assembly 173
5.3 Mass Production 178
5.3.1 Without Pre-cut and Formed Components 178
5.3.2 Automatic Positioning Tables 179
5.3.3 Using Pre-cut and Formed Components 180
5.4 Lead Preforming 180
5.4.1 Types of Preformed Shape — Axial Components 181
5.4.2 Manual Preforming — Axial Components 186
5.4.3 Preforming Equipment for Axial Components 186
5.4.4 Preforming Non-axial Leaded Components 190
5.5 Production Aids 194
5.5.1 Layout Memorisation 195
5.5.2 Stage Assembly 196
5.5.3 Sequence Assembly 197
5.5.4 Component Sequencing 199
5.6 Visual Aids 200
5.6.1 Screen Printing 200
5.6.2 Slide Projection 202
5.6.3 Lamp Displays 202
5.6.4 LED Displays 203

5.6.5 Optical Fibre Displays 204
5.6.6 Laser Scanning Systems 204
5.7 Assembly Inspection 206
5.7.1 Visual Inspection 206
5.7.2 Equipment Assisted Inspection 207

CHAPTER SIX

Automatic Assembly — Conventional Components 209

6.1 Introduction 209
6.1.1 Economics of Automation 209
6.1.2 The ‘Mechanical Horse’ 210
6.2 Early Automation 212
6.2.1 Semi-automatic Equipment 212
6.2.2 The Transfer Line 214
6.3 Component Packaging 215
6.3.1 Axial Component Taping 215
6.3.2 Radial Component Taping 218
6.3.3 DIP Components 221
6.3.4 Odd Components 222
6.4 Machine Types 222
6.4.1 Dedicated Inserters 223
6.4.2 Off-line Sequencing 224
6.4.2.1 Axial Component Sequencing 224
6.4.2.2 Sequence Verifiers 228
6.4.3 In-line Sequencing 228
6.4.3.1 Chain Sequencing 228
6.4.3.2 Air Delivery 229
6.4.3.3 Shuttle Delivery 230
6.4.3.4 Gravity Chute 230
6.4.3.5 Sort and Place 232
6.4.3.6 Pick-and-place 232
6.4.4 X-Y Tables and Rotary Tables 232
6.4.5 Positioning Aids — Optical Verifiers 234
6.4.6 Cutting and Clinching 235
6.4.7 Insertion Verification On-line 236
6.4.8 Control Unit 237
6.5 Axial Component Insertion Machines 238
6.5.1 Inserters versus Sequence-inserters 239
6.5.2 Fixed versus Variable Centre Distance 241
6.5.3 Insertion Programs 242
6.5.4 Insertion Cycle 245
6.5.5 Typical Axial Inserters 247
6.6 Radial Component Insertion Machines 248
6.6.1 Machine A 248
6.6.2 Machine B 249
6.6.3 Machine C 249
6.7 Dual Inserters 250
6.8 DIP Insertion Machines 250
6.8.1 Component Feeding 252
6.8.2 Insertion Cycle 253
6.8.3 Typical DIP Sequencer-inserters 254
6.8.3.1 Example A 254
6.8.3.2 Example B 254
6.8.3.3 Example C 254
6.8.3.4 Example D 255
6.8.3.5 Equipment Manufacturers 255

6.9 Odd Component Insertion Machines 255
6.9.1 Dedicated Insertion Machines for Odd Components 256
6.9.2 General Purpose Robots 257
6.10 Assembly Inspection 259
6.10.1 Visual Inspection 260
6.10.2 Inspection Equipment 261
6.11 Board Handling 262

CHAPTER SEVEN

Automatic Assembly — Surface Mount Components 266

7.1 Types of Surface Mount Assembly (SMA) 266
7.1.1 Single-sided SMA 267
7.1.2 Double-sided SMA 269
7.1.3 Mixprint — SMDs One Side Only 269
7.1.4 Full Mixprint 272
7.2 Surface Mounting Adhesives 272
7.2.1 Requirements for Adhesives 274
7.2.2 Application Methods 276
7.2.2.1 Pin Transfer 276
7.2.2.2 Syringe 280
7.2.2.3 Screen Printing 281
7.2.3 Adhesive Dot Criteria 281
7.2.4 Storage of Boards 283
7.2.5 Adhesive Curing 283
7.3 Solder Pastes 285
7.4 Conductive Adhesives 286
7.5 Component Mounting 287
7.5.1 Evolution of Pick-and-place Equipment from Manual Assembly 288
7.5.2 Automatic Mounting 289
7.5.3 An Automatic Mounting Machine 291
7.5.4 PB Loading and Positioning 292
7.5.5 Component Feeding 293
7.5.5.1 Rails and Tubes 295
7.5.5.2 Vibratory Bowl 295
7.5.5.3 Vibrating Conveyor 296
7.5.5.4 Hopper 296
7.5.5.5 Tape on Reel 297
7.5.5.6 Others 297
7.5.6 Application Heads 297
7.5.6.1 Picking Up 298
7.5.6.2 Centring 299
7.5.6.3 Rotation 299
7.5.6.4 Testing 300
7.5.6.5 Placement Control 301
7.5.6.6 Teach-in Options 302
7.5.6.7 Bad Circuit Detector 303
7.5.6.8 Optical Recognition Equipment 303
7.5.6.9 Turret Heads 303
7.5.6.10 Adhesive Applicators 304
7.5.7 Control 304
7.5.8 Software Packages 307
7.6 Mounting Equipment 308
7.6.1 Table-top 308
7.6.2 Pick-and-place 309
7.6.2.1 Examples of Sequential Pick-and-place Machines 310
7.6.3 Multiple Arm Pick-and-place 315

7.6.4 Parallel Equipment 316
7.6.5 Parallel-sequential Equipment 321
7.7 Ancillary Equipment 322
7.7.1 Curing Ovens 322
7.7.2 General Purpose Robots 324
7.8 Integrated Assembly Lines 324
7.9 Equipment Selection 326

CHAPTER EIGHT

General Principles of Design and Layout (of Printed Board Assemblies) 328

8.1 General 328
8.2 Basic Definitions 329
8.3 Classification of PBs 334
8.4 Initial Assessment 340
8.5 Tentative Dimensioning 342
8.5.1 Vertical Mounting 343
8.6 Working Out the Volume 344
8.7 Multiple Board Assembly 345
8.7.1 Advantages of a Single Board Solution 345
8.7.2 Advantages of a Multiple Board Solution 345
8.7.3 Point-to-point Wiring 346
8.7.4 Soldered Backplanes 348
8.7.5 Book Connection 349
8.7.6 Motherboard 350
8.7.7 Soldered Add-ons 351
8.7.8 Sandwich 351
8.7.9 Others 352
8.8 Design of Boards 352
8.8.1 Partition of the Assembly 352
8.8.1.1 Number of Connections 353
8.8.1.2 Assembly Technology 353
8.8.1.3 Making a Layout 353
8.8.1.4 Testability and Reparability 354
8.8.1.5 Maintainability 354
8.8.1.6 Environment 355
8.8.1.7 Logistics 355
8.8.1.8 Costs 356
8.8.2 Gross and Net Area 356
8.8.3 PIH Assembly 359
8.8.4 SMC Assembly 364
8.8.5 Mixprint Assemblies 370
8.8.6 Heavy Components 371
8.8.7 Other Points 372
8.9 Conductor Dimensioning 373
8.10 Further Reading 382

CHAPTER NINE

Layout of Printed Circuit Boards 384

9.1 Introduction 384
9.1.1 Manual Layout 384
9.1.2 Amateur’s Layout 387
9.1.3 Manual Drawing of Artworks 387
9.1.4 Master Drawing 393
9.1.5 Component Map 395

9.2 Automated Production of Films 396
9.2.1 Digitising 396
9.2.2 Editing 397
9.2.3 Photoplotting 398
9.3 General Principles 400
9.3.1 Why Use a Grid? 401
9.3.2 Grid Selection 402
9.3.3 Grid Sizes in Common Use 404
9.3.4 A Bad Example 409
9.3.5 A Good Example 413
9.4 PIH (Pin-in-hole) Components 414
9.4.1 Axial Components 415
9.4.2 Other Discrete Components 418
9.4.3 Integrated Circuits 419
9.5 Surface Mounted Components 421
9.5.1 Is a Grid Essential? 423
9.5.2 Minimum Distance 423
9.5.3 Dimensioning of Lands 425
9.5.3.1 Wave Soldering 425
9.5.3.2 Reflow Soldering 428
9.5.4 Footprints 428
9.5.4.1 Chip SMD Footprints 429
9.5.4.2 MELF Component Footprints 429
9.5.4.3 Other Discrete SMC Footprints 430
9.5.4.4 SM Integrated Circuit Footprints 431
9.6 Multiple Boards 432
9.7 Conclusion 433

CHAPTER TEN

CAD/CAM 439

10.1 Introduction 439
10.2 Input Formats 439
10.2.1 Pin List 439
10.2.2 Schematic Entry 440
10.2.2.1 Style of Schematic Entry 443
10.2.2.2 Hierarchical Design 443
10.2.2.3 Libraries 443
10.2.3 No Format Supplied 444
10.3 Simulation 444
10.3.1 PAL, PLA and ASIC 445
10.4 Printed Board Layout Requirements 446
10.4.1 Capability Required 446
10.4.1.1 Co-ordinate System 446
10.4.1.2 Resolution 446
10.4.1.3 Layers 446
10.4.1.4 Track/Trace Widths 447
10.4.1.5 Pad Shapes 447
10.4.2 Placement 447
10.4.2.1 Autoplacement 448
10.4.3 Routing 449
10.4.3.1 Manual Routing 449
10.4.3.2 Autoroute Styles 449
10.4.4 Design Checking 452

10.4.5 Modifications 454
10.4.6 Schematic Annotation 455
10.4.7 Automatic Test 455
10.4.8 Mechanical Drawing 456
10.5 Outputs 456
10.5.1 Schematics 456
10.5.2 Layouts 457
10.5.3 Photoplotting 457
10.5.3.1 Pen Plotters 458
10.5.3.2 Matrix Plotters 459
10.5.3.3 Laser Printers 460
10.6 Computer Aided Manufacturing (CAM) 460
10.7 Interfaces 461
10.8 The Processing Platform 462
10.8.1 The Personal Computer (PC) 462
10.8.2 Memory Needs 463
10.8.3 Data Transfer 464
10.8.4 Machine Architecture 464
10.8.5 Graphics 465
10.8.6 Networks and Workstations 465
10.8.7 Processor Performance 465
10.9 Man-machine Interaction 466
10.10 Choosing a CAD System 467

CHAPTER ELEVEN

Thermal Management Aspects 469

11.1 Introduction 469
11.1.1 Thermal Design 469
11.1.1.1 The Influence of Components and Cooling Methods on Temperature 470
11.1.1.2 The Rôle of Temperature Prediction 471
11.1.1.3 How Far Thermal Design? 471
11.1.2 Format of this Chapter 471
11.2 Heat Transfer Mechanisms and Temperature Effects 472
11.2.1 Mechanisms of Heat Transfer 473
11.2.1.1 Conduction 473
11.2.1.2 Convection 473
11.2.1.3 Radiation 473
11.2.1.4 Phase-change Heat Absorption 474
11.2.2 Difficulties Involved in Evaluating the Effects of Temperature on Reliability and Performance 474
11.2.3 Approach to Thermal Design 475
11.2.4 Designing for Reliability and Performance 476
11.2.4.1 Will the System Operate? 476
11.2.4.2 Can the System be Improved? 477
11.2.4.3 Relationship Between Temperature and Performance 477
11.3 Printed Board Construction and Examples 478
11.3.1 Types of Printed Board 478
11.3.1.1 A Combination of Circuit Board Types 479
11.3.2 Circuit Board Thermal Properties 480
11.3.2.1 The Thermal Conductivity of Basic Epoxide Printed Boards 480
11.3.2.2 Effective Thermal Conductivity of Printed Circuit Boards Having a High Thermal Conductivity Core 482
11.3.2.3 Surface Heat Loss and Gain from Boards Having a High Thermal Conductivity Core 483

11.3.2.4 Poor Thermal Conductivity Boards Having Designed Heat Pathways Bonded to Their Surface 483
11.3.3 Circuit Board Examples for Illustrating the Estimation of Effective Thermal Properties 485
11.4 'First Look' Methods of Circuit Board Thermal Design 488
11.4.1 'First Look' Temperature Prediction for Circuit Boards Without Surface Heat Loss 489
11.4.1.1 Concentration of Heat Generation at the Mean Distance from the Heat Sink 489
11.4.1.2 Uniform Distribution of Heat Generation with No Surface Heat Loss 490
11.4.1.3 Effect of Component Size 491
11.4.1.4 Estimate of Component Area Temperatures 492
11.4.2 'First Look' Temperature Prediction for Surface-cooled Circuit Boards 493
11.4.2.1 Simplification of Temperature Profile Approach 494
11.4.2.2 Exact Evaluation of Uniformly Heated Circuit Board with Surface Heat Loss 498
11.4.2.3 Effect of Component Size Under Surface Heat Loss Conditions 500
11.4.2.4 Estimate of Component Area Temperatures for Surface Cooling 502
11.4.3 General Features of Temperature Prediction Using 'First Look' Methods 502
11.4.3.1 Area of Sparse Power Dissipation 503
11.4.3.2 Poor Thermal Conductivity Circuit Boards 504
11.4.4 'First Look' Temperature Prediction for Circuit Boards Cooled by a Rear-mounted Heat Sink 506
11.4.5 'First Look' Temperature Values for Components 509
11.5 More Accurate Methods of Estimating the Temperatures Reached in Circuit Boards 510
11.5.1 Balanced Circuits 510
11.5.1.1 Balanced Circuits Mounted on Conduction-only Cooled Circuit Boards 512
11.5.1.2 Balanced Circuits Mounted on Surface-cooled Circuit Boards 513
11.5.2 Excess Temperature Estimation 514
11.5.2.1 A Graphical Method of Temperature Prediction for Conduction-cooled Circuit Boards 514
11.5.2.2 Temperature Estimates for Surface-cooled Circuit Boards 518
11.5.3 Estimates of Temperatures Arising on Circuit Boards Cooled by a Rear-mounted Heat Sink 518
11.5.4 Temperature Values for Components 519
11.6 Desk-computer-supported Circuit Board Thermal Design 519
11.6.1 Defects of Computer Packages when used for Thermal Design 519
11.6.2 Two Reliable Computer-assisted Methods 521
11.6.2.1 A Method for Edge-cooled Circuit Boards 521
11.6.2.2 A Method for Rear-cooled Circuit Boards 525
11.7 Convection Cooling 525
11.7.1 The Mechanisms of Convection 525
11.7.1.1 Design Features of Air-cooled Systems 526
11.7.2 Accuracy of Heat Transfer Coefficients 527
11.7.2.1 Influence of Changes in Air Temperature and Edge-connector Efficiency 529
11.7.3 Packages with an Attached Heat Sink 529
11.7.3.1 The Use of Die-cast Zinc Heat Sinks 529
11.7.4 Cooling Within the Cabinet 530
11.8 Other Aspects of Thermal Design 534
11.8.1 Thermal Expansion Mismatch 534
11.8.1.1 Soft Solder Joint Embrittlement 534
11.8.1.2 Component Features 534
11.8.2 Liquid Cooling 535

11.8.2.1 Convection Cooling Using Liquids 535
11.8.2.2 Phase-change Cooling by Nucleate Boiling 535
11.8.3 Heat Pipes 535
11.9 Postscript 536

CHAPTER TWELVE

Soldering 538

12.1 Fundamentals of Soldering 538
12.2 Making a Solder Joint 539
12.3 Cost Breakdown (The Economics of Soldering) 539
12.3.1 Manufacturing Costs 539
12.3.2 Materials Cost versus Failure Cost 540
12.3.3 Machine Cost 541
12.3.4 Quality Costs 541
12.4 Problem Areas in Soldering 542
12.5 Prerequisites for a Sound, Reliable Solder Joint 543
12.5.1 The Design Phase 544
12.5.1.1 Placement of the Solder Joint 544
12.5.1.2 The Joint Design (Dimensions, Geometry and Tolerances) 544
12.5.1.3 Thermal Problems 545
12.5.1.4 Repair 545
12.5.1.5 Demands Placed on the Solder Joint in Manufacturing, Storage, Transport and Operation
12.5.1.6 Properties of the Materials Used 546
12.5.1.7 Choice of Solder and Flux 546
12.5.1.8 Choice of Soldering Method 547
12.5.2 Preproduction Phase 547
12.5.2.1 Equipment and Workshop 547
12.5.2.2 Personnel 548
12.5.2.3 Preparation for Soldering 548
12.5.2.4 Preproduction Checks 548
12.5.2.5 Storage of Material 548
12.5.3 Production Phase 548
12.6 Metallurgy 549
12.6.1 Soldering 549
12.6.2 Dissolution of Metals 549
12.6.3 Solidification of Solder 552
12.6.4 Intermetallic Phases 552
12.6.5 Diffusion 552
12.7 Wetting 555
12.8 Thermal Considerations 558
12.9 Solderability 560
12.9.1 General 560
12.9.2 What is Solderability? 560
12.9.3 The Advantages of Solderability Testing 561
12.9.4 Preservation of Solderability 561
12.9.5 Solderability Testing Methods 563
12.9.5.1 The Wetting Balance Method 564
12.9.5.2 The Scanning Method 565
12.9.5.3 The Workshop Method 567
12.9.5.4 The Solder Globule Method 568
12.9.5.5 The Spread Test 569
12.9.5.6 Testing of Printed Boards 570
12.9.5.7 Artificial Ageing Methods 572

12.9.5.8 Analysing Solderability Results 574
12.9.5.9 Solderability Testing *versus* Actual Performance 576
12.9.6 Correcting Bad Solderability 576
12.10 Quality and Reliability 577
12.10.1 Education, Information, Training 579
12.10.1.1 Management 579
12.10.1.2 Designers 579
12.10.1.3 Soldering Operators and Inspectors 579
12.10.2 Statistical Considerations 580
12.10.2.1 The Problem of the Great Number of Solder Joints 580
12.10.2.2. How Exact is a Measured Value? 581
12.10.2.3 SPC — Statistical Process Control 582
12.10.3 Inspection of Solder Joints 586
12.10.3.1 Visual Inspection 586
12.10.3.2 Automated Optical Inspection (AOI) 587
12.10.3.3 X-ray Inspection 589
12.10.3.4 Ultrasonic Inspection 589
12.10.3.5 Thermal Inspection 589
12.10.4 Soldering Defects 590
12.10.4.1 What is a Soldering Defect? 590
12.10.4.2 Soldering Defects and Failure Rate 591
12.10.4.3 Solder-filled Through-plated Holes or not? 592
12.10.4.4 Defect Terminology 594
12.10.5 Expert Systems in Soldering 598
12.11 Mounting Methods 600
12.12 Classification of Assemblies 600
12.13 Health and Safety 601
12.13.1 Solders 601
12.13.2 Fluxes 602
12.3.3 Soldering Equipment 602
12.14 Terms and Definitions 603
12.14.1 General Definitions Related to Soldering 603
12.14.2 Terms Related to Soldering 604
12.14.3 Time-temperature Terms 604
12.14.4 Terms Related to Joint Form and Size 606
12.14.5 Terms Related to Solder Joints 607
12.14.6 Materials to be Joined 607
12.14.7 Flux Terms 608
12.14.8 Solder Terms 609
12.14.9 Soldering Aid Material 610
12.14.10 Soldering Methods and Processes 610
12.14.11 Quality Terms 610
12.14.12 Soldering Defects 611

CHAPTER THIRTEEN

Materials Used in Soldering 614

13.1 General 614
13.2 Base Materials 614
13.3 Surface Treatments 614
13.3.1 Methods of Surface Treatment 615
13.3.2 Mechanism of Bonding 615
13.3.3 Layer Structure 615
13.3.3.1 The Bond 616
13.3.3.2 Diffusion Barriers 617
13.3.3.3 Protective Layers 617
13.3.3.4 Materials Build-up for Soldering 617

13.3.4 Solderable Coatings 618
13.3.4.1 Electrolytic Tinning 618
13.3.4.2 Hot Tinning 619
13.3.4.3 Nickel 620
13.3.4.4 Gold 620
13.3.4.5 Silver, Silver-palladium Plating 628
13.3.4.6 Problems in Plating 629
13.3.4.7 Points to be Checked 629
13.4 Solder for Electronic Purposes 629
13.4.1 General 629
13.4.2 Properties of Solder 630
13.4.3 Requirements Specified for Solders 630
13.4.4 Low Melting Point Solders 631
13.4.5 High Melting Point Solders 631
13.4.6 Step Soldering 632
13.4.7 Impurities in Solder 632
13.4.7.1 Copper 635
13.4.7.2 Gold 636
13.4.7.3 Silver 636
13.4.7.4 Iron 636
14.7.4.5 Nickel 637
13.4.7.6 Bismuth 637
13.4.7.7 Antimony 637
13.4.7.8 Arsenic 637
13.4.7.9 Aluminium, Zinc and Cadmium 637
13.4.7.10 Oxygen 638
13.4.7.11 Sulphur 638
13.4.7.12 Phosphorus 639
13.4.7.13 Dross 639
13.5 Fluxes 639
13.5.1 Definition of Fluxes 639
13.5.2 General 640
13.5.3 Classification of and Tests on Fluxes 640
13.5.4 Resin Fluxes 644
13.5.5 Colophony (Rosin) 644
13.5.6 Activated Rosin Fluxes 644
13.5.7 Halogen-containing Fluxes and Corrosion 645
13.5.8 Water-soluble Fluxes 645
13.5.9 Gaseous Fluxes and Soldering Without Fluxes 646
13.5.10 Low Solid Content Flux, No Residue Flux 647
13.5.11 Cleaning Off Fluxes and Flux Residues 647
13.6 Solder Pastes 648
13.6.1 General 648
13.6.2 Solder Balling 648
13.6.3 Viscosity 649
13.6.4 Slump 649
13.6.5 Corrosion of Residues 649
13.6.6 Assessment of Shape and Size of Solder Powder Particles 649
13.6.7 Storage of Solder Pastes 650
13.7 Properties of Solder Influencing the Solder Joint 650
13.7.1 Cracks in the Solder Joint 650
13.7.2 Mechanisms of Solder Joint Failure 651
13.7.3 The Different Types of Strength 653
13.7.4 Fatigue 656
13.7.4.1 Lifetime Prediction 658
13.7.4.2 Testing of Fatigue Properties 662
13.7.4.3 Measures to Increase the Lifetime of a Solder Joint 662

13.7.5 Tin Pest 665
13.7.6 Whiskers 666

CHAPTER FOURTEEN

Manual Soldering 668

14.1 Manual Soldering 668
14.2 The Soldering Iron 668
14.2.1 How Does a Soldering Iron Work? 669
14.2.2 The Soldering Iron Tip 671
14.2.3 The Wear of the Soldering Iron Tip 673
14.2.4 Heat Flow from the Iron to the Workpiece 673
14.2.5 Measuring the Tip Temperature 675
14.2.6 The Rating of the Soldering Iron 676
14.2.7 Tip Temperature and Heat Output from the Tip 676
14.2.8 Criteria for a Soldering Iron 677
14.2.9 Soldering Iron Support 679
14.2.10 'Tin Surplus' Collector 679
14.3 Soldering Printed Board Assemblies 680
14.3.1 Boards, Components and Solder Requirements 680
14.3.2 Operator and Working Conditions 680
14.3.3 Soldering Conditions 680
14.3.4 Making the Joint 681
14.4 Rework and Repair 681
14.4.1 Repair of Conductors on the Board 682
14.4.2 Repair of Solder Joints 682

CHAPTER FIFTEEN

Mass Soldering 685

15.1 General Considerations 685
15.1.1 Heat Supply 686
15.1.2 Temperature Profiles 686
15.1.3 Reflow Soldering 687
15.1.4 Controlled Atmosphere Soldering 688
15.2 The Mass Soldering Machine 690
15.2.1 The Soldering Fixture 691
15.2.2 The Conveyor 691
15.2.3 The Fluxing Station 692
15.2.3.1 Brush Fluxing and Dip Fluxing 693
15.2.3.2 Rotary Brush Fluxing 693
15.2.3.3 Wave Fluxing 693
15.2.3.4 Foam Fluxing 694
15.2.3.5 Spray Fluxing 694
15.2.3.6 Density Control 695
15.2.4 The Preheating Station 696
15.2.5 The Soldering Station 698
15.2.5.1 Solder Replacement 699
15.2.6 The Cleaning Station 700
15.2.7 Process Control Aids 700
15.2.7.1 Temperature Indication 700
15.2.7.2 Soldering Process Testing 700
15.2.8 The Maintenance of a Soldering Machine 701
15.2.9 Buying a Soldering Machine 703
15.3 Dip Soldering 704
15.4 Drag Soldering 704
15.5 Wave Soldering 705

15.5.1 The Wave Form and the Nozzles 708
15.5.2 Wave Soldering Machines for SMT 709
15.5.2.1 The Double Wave Soldering Machine 709
15.5.2.2 The Pulsed Wave Soldering Machine 709
15.5.3 Oil in the Wave 710
15.6 Infra-red Soldering 711
15.7 Convection and Forced Convection Soldering 711
15.8 Vapour Phase Soldering or Condensation Soldering 712
15.9 Laser 715
15.9.1 Types of Laser used for Soldering 715
15.9.2 Pulsed and CW Lasers 716
15.9.3 Controlled Laser for Soldering 716
15.9.4 The Heat Flow in Metals Radiated by Laser 716
15.9.5 The Laser Solder Joint 717
15.9.6 Maximising the Advantages of Laser Soldering 718
15.9.7 Areas for Laser Soldering 719
15.9.8 The Economics of Laser Soldering 720
15.10 Light Soldering 720
15.11 Hot Bar Soldering 721
15.12 Hotplate Soldering 722
15.13 Belt Soldering 722
15.14 Hot Gas Soldering 722
15.15 Furnace Soldering 723
15.16 Robot Soldering 723
15.17 Ultrasonic (US) Soldering 724
15.18 High Frequency (HF) Soldering 724

CHAPTER SIXTEEN

Microjoining Methods 726

16.1 Introduction 726
16.2 The Principles of Metallurgical Joining Methods 727
16.2.1 Soldering Methods 728
16.2.2 Welding Methods 728
16.2.2.1 Resistance Welding 729
16.2.2.2 Diffusion Welding 729
16.2.2.3 Ultrasonic (US) Welding 731
16.2.3 The Equipment 731
16.2.4 The Materials 732
16.2.4.1 Materials to be Joined 732
16.2.4.2 Chips, Dice or Die 732
16.2.4.3 Electrodes and Thermodes 733
16.2.5 Process Control 734
16.3 Different Joining Methods 734
16.3.1 Wire Bonding 734
16.3.2 Tape Automated Bonding (TAB) 735
16.3.3 Flip-chip 738
16.3.4 Beam Lead 739
16.3.5 Isothermal Soldering 740
16.3.6 Wire Wrap 740
16.3.7 Explosive Welding 741
16.3.8 Adhesives 741
16.3.9 Chip-on-board (COB) and Multichip Module (MCM) 742
16.3.10 Board Wiring Techniques 742
16.3.10.1 Impulse Bonded Wiring 742
16.3.10.2 Stitchwire 743
16.3.10.3 Multiwire and Microwire 743